








# POLISHABLE OVERLAYS PROCESS STEPS

TOOL	GRIT	DESCRIPTION	IMAGE
1 First-Cut Premium 4 Seg	30/40 or 60/80	<b>Expose the Floor</b> <i>*Choose grit depending on cure time and desired aggregate exposure</i>	
2 BSD Transitional or Premium 8 Seg	50	Expose and Hone the Floor	
3 BSD Transitional or Premium 8 Seg	100	Refined Honing	
4 BSD Transitional or Premium 8 Seg	200	Exposed/Flat Finish	
5 Resin, TC Pad or Dry Flex Pad	400	Exposed/Satin Finish (Honed)	
6 Resin, TC Pad or Dry Flex Pad	800	Polished	
7 Resin, TC Pad or Dry Flex Pad	1500	Highly Polished	
8 Easy Edge™, Edge Flex™, and EdgeXcel	50 100 400	Edge Honing and Polishing	