

SPEEDSHIFT

Meet the Speedshift: a new attachment option for all Terrco grinders! Made of heat-resistant plastic, the Speedshift comes with our floor tooling already mounted onto the adaptor for quick installation and ultimate convenience. Once the puck wears down, the entire tool can be easily discarded for hassle-free replacement. Available in Premium 8 Segs and BSD Transitional pucks.

Features

- Heat-resistant plastic
- Polishing tool comes glued to adaptor
- Compatible with all Terrco grinders
- Throw-away when done
- Product details of the 8 Seg and BSD apply



Item #	Description	Size	Grit
73708B	Speedshift Resins - Dry	3"	200
73718B	Speedshift Resins - Dry	3"	400
73728B	Speedshift Resins - Dry	3"	800
73738B	Speedshift Resins - Dry	3"	1500
73748B	Speedshift Resins - Dry	3"	3000
8645WS	Speedshift Resins - Wet	3"	200
8646WS	Speedshift Resins - Wet	3"	400
8647WS	Speedshift Resins - Wet	3"	800
8648WS	Speedshift Resins - Wet	3"	1500
8649WS	Speedshift Resins - Wet	3"	3000

Item #	Description	Size	Grit	Bond	Concrete Hardness
7181B	8 Segment Transitional	3"	30	Standard	Soft to Hard
7182	8 Segment Transitional	3"	50	Standard	Soft to Hard
7183	8 Segment Transitional	3"	100	Standard	Soft to Hard
7184	8 Segment Transitional	3"	200	Standard	Soft to Hard
7185B	8 Segment Transitional	3"	400	Standard	Soft to Hard
72208B	8 Segment Transitional	3"	30	Soft	Very Hard
72300	8 Segment Transitional	3"	50	Soft	Very Hard
72302	8 Segment Transitional	3"	100	Soft	Very Hard
72601	8 Segment Transitional	3"	200	Soft	Very Hard
72505	8 Segment Transitional	3"	30	Hard	Soft
72506	8 Segment Transitional	3"	50	Hard	Soft
72507	8 Segment Transitional	3"	100	Hard	Soft
72508	8 Segment Transitional	3"	200	Hard	Soft
72509	8 Segment Transitional	3"	400	Hard	Soft
71304	BSD Transitional	3"	30	Standard	Soft to Hard
71300	BSD Transitional	3"	50	Standard	Soft to Hard
71305	BSD Transitional	3"	80	Standard	Soft to Hard
71207	BSD Transitional	3"	100	Standard	Soft to Hard
71307	BSD Transitional	3"	200	Standard	Soft to Hard
71301	BSD Transitional	3"	400	Standard	Soft to Hard
71603	BSD Transitional	3"	30	Soft	Very Hard
71604	BSD Transitional	3"	50	Soft	Very Hard
71605	BSD Transitional	3"	80	Soft	Very Hard
71606	BSD Transitional	3"	100	Soft	Very Hard
71607	BSD Transitional	3"	200	Soft	Very Hard
71608	BSD Transitional	3"	400	Soft	Very Hard
86405	BSD Transitional	3"	30	Hard	Soft
86406	BSD Transitional	3"	50	Hard	Soft
86407	BSD Transitional	3"	100	Hard	Soft
86408	BSD Transitional	3"	200	Hard	Soft
86409	BSD Transitional	3"	400	Hard	Soft